

5/15

SPLIT

DART AEROSPACE LTD	Work Order:	22590 A
Description: Lanyard Assembly	Part Number:	D2690- X
Drawing: D2690 Rev. B1 B2	Qty:	X = 5 5

Step	Location	Procedure	By	Date	Qty
1	EXPEDITING	Open W/O Complete X in the title block with the required length for the lanyard.	HA	05.03.02	5
2	STORES	Pick: Qty Part Number Description Batch 2 CBL-460 Loop Sleeve M16713 X" + 2.5" CBL-1240 Cable M7430 M16713 Value for X is stated above in title block	SB	05/05/05	5
3	METAL	Assemble as per Dwg D2690	SB	05/05/05	5
4	QC	Inspect Level 7	2	05-05-05	5
5	STORES	Identify and stock	C2	05/05/05	5
6	EXPEDITING	Close W/O Cost / part: 6.79 5ur 05/05/06 Inspect level 21 3.24	HA	05.05.10	5

Rev	Date	Change	Created By	Approved
A	98.05.08	New Issue	KB	
B	99.02.09	Added Inspection Level	DM	
C	01.08.24	Removed Manufacturer Release Certification	SM	

RELEASED

01.08.24

RF
03.04.01

7.625

W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE		By	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action			Verification Section C	Approval Design Mgr	Approval QC Inspector
			Initial Design Mgr	Action Description Design Mgr	Sign & Date			

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____


NOTE: Date & initial all entries

QA: N/C Closed: _____ Date: _____



DESIGN <i>ME</i>	DRAWN BY <i>KE</i>	DART AEROSPACE LTD VICTORIA INTERNATIONAL AIRPORT, CANADA	
CHECKED <i>ME</i>	APPROVED <i>BW</i>	DRAWING NO. D2690	REV. B SHEET 1 OF 1
DATE 97.10.02		TITLE LANYARD ASSEMBLY	SCALE NTS
A	97.07.03	NEW ISSUE	
B	97.10.02	REVISED NOTE FOR ADDITIONAL LENGTH	
B1	01.08.20	ADD NOTE TO REMOVE 2.25" OF SLEEVE	
B2	04.06.24	ADDED TOLERANCE	

RELEASED
971003 KE
TYP A374



D2690-X

X = LENGTH IN INCHES

SHO...
UNCONT... COPY
SUBJECT T...
WITHOUT NOTICE

WORK ORDER
NO. 22590

NOTE: CUT CABLE 2.50* INCHES LONGER THAN 'X' LENGTH. FOLD ENDS TIGHT TO 'X' LENGTH AND CRIMP WITH SLEEVE AT END OF LOOSE END OF CABLE WITH CBL-705 CRIMPING TOOL.
*ADDITIONAL LENGTH MAY BE NECESSARY IN SOME APPLICATIONS. CUT AS REQUIRED.

NOTE: IN SOME CASES, END HAS TO BE CRIMPED AFTER ASSEMBLY WITH ATTACHING PARTS.

Job Costing Report

Dart Aerospace Ltd.
Hawkesbury

Mar 01, 2005
11:19 am

Work Order No : 0022590
Project Name : D2690-5
Project For : WK515
Work Order Type : Main
Main WO Number :
House Part Number : D2690-5
Description : Lanyard ass'y
Manufactured : Yes
Amount Req'd : 30
Amount Done : 0
Start Date : 03-01-05
Est Finish Date : 03-30-05
Act Finish Date :
Drawings Req'd : No
Ok for Approval :
Approval Rec'd :

Department Code:
Burden Flags : NNNNNNNN
WO Status : Open
Invoice State : Not Invoiced
Invoice Date :
Invoice Number :
Invoice Amount : 0.00

Order Entry No :
OE Value : 0.00

Est Margin : 0.000%
Actual Margin : 0.000%

\$0 Posted to Finished Goods

	Estimated	Actual	Var. %	Posted	To Post
Material Cost :	0.00	0.00	0.00	0.00	0.00
Engineering Hours :	0.00	0.00	0.00		
Engineering Cost :	0.00	0.00	0.00	0.00	0.00
Production Hours :	0.00	0.00	0.00		
Production Cost :	0.00	0.00	0.00	0.00	0.00
Packaging Hours :	0.00	0.00	0.00		
Packaging Cost :	0.00	0.00	0.00	0.00	0.00
OverHead Hours :	0.00	0.00	0.00		
OverHead Cost :	0.00	0.00	0.00	0.00	0.00
CNC Hours :	0.00	0.00	0.00		
CNC :	0.00	0.00	0.00	0.00	0.00
Misc. Hours :	0.00	0.00	0.00		
Misc. :	0.00	0.00	0.00	0.00	0.00
Burden :	0.00	0.00	0.00		
Total Cost :	0.00	0.00	0.00		
Margin :	0.000	0.000			
Selling Cost :	0.00	0.00			

	Estimated	Actual
Labour Hrs/Amount Done :	0.00	0.00
Profits/(Loss) :	0.00	0.00